

COMMUTER PARKING LOTS

Fall, 2008 Data

Municipality	Location (1)	Capacity	Vehicle Count - Oct. 2008		Five Year Comparison				
			Count	Percent Full	Oct, 2007	Nov, 2006	Nov, 2005	Oct. 2004	Nov. 2003
Branford	I-95 at Maintenance Garage (exit 56)	40	7	18%	7	6	2	5	4
	Route 1 at Cherry Hill	124	37	30%	27	31	24	22	10
	I-95 at Route 1 (exit 55)	70	32	46%	37	30	21	20	9
	Branford Railroad Station	205	209	102%	186	223	199	137	73
East Haven	Route 1 at Kimberly Avenue (West Lot)	29	28	97%	19	14	7	16	8
	Route 1 at Kimberly Avenue (East Lot)	20	20	100%	12	9	10	11	6
Guilford	I-95 at Route 77 (exit 58 - East Lot)	113	4	4%	6	8	2	13	6
	I-95 at Route 77 (exit 58 - West Lot)	45	16	36%	16	12	9	17	19
	I-95 at Goose Lane (exit 59)	58	11	19%	14	21	13	17	5
	I-95 at Route 1 (exit 57)	20	42	210%	23	9	14	3	10
	Guilford Railroad Station	176	193	110%	198	129	179	122	82
Madison	I-95 at Route 79 (exit 61)	197	50	25%	26	30	34	33	25
	Madison Railroad Station	110	183	166%	152	161	184	141	91
Meriden	I-691 at Lewis Avenue (exit 6)	55	closed	0%	25	21	17	14	11
	I-691 at State Street	31	closed	0%	0	3	1	0	0
	I-91 at Bee Street	72	26	36%	27	20	24	20	24
Milford	I-95 at Old Gate Lane (exit 40) - Lot 2	75	33	44%	41	7	8	2	8
	I-95 at School House Road (exit 35)	46	22	48%	13	17	14	10	3
	Route 1 at Milford Connector	25	16	64%	23	24	15	15	8
	Route 15 at Wheelers Farms Road (exit 55)	59	33	56%	34	44	27	33	9
	Milford Railroad Station at High Street	444	608	137%	608	473	352	333	327
New Haven	Union Station Garage (1)	1037	1082	0%	1083	1091	998	1125	1005
North Haven	Route 40 at Divine Street	109	112	0%	113	49	67	46	34
	Route 5 at Divine Street	103	113	0%	111	39	57	40	49
Orange	Route 15 at Route 34 (exit 58)	154	100	0%	93	105	62	79	76
Wallingford	Route 5 at Wharton Brook Connector	79	30	0%	31	20	29	28	20
	Route 15 at Route 5 (exit 66E)	81	53	0%	52	24	37	39	26
	I-91 at Route 68 (exit 15)	105	40	29%	36	35	16	0	38
	Wallingford Railroad Sta	25	12	212%	14	12	6	9	17
West Haven	I-95 at Route 122 (exit 43)	74	30	0%	32	10	25	16	15
TOTAL		3,781	3,112	82%	3,059	2,677	2,453	2,366	2,018

(1) data for Union Station supplied by New Haven Parking Authority

Table 1

COMMUTER PARKING LOTS
Current Use & Peak Utilization
Fall, 2008

Municipality	Location	Capacity	Current Count		
			Date	Vehicle Count	Percent Full
Branford	I-95 at Maintenance Garage (exit 56)	40	10/15	7	18%
	Route 1 at Cherry Hill	124	10/15	37	30%
	I-95 at Route 1 (exit 55)	70	10/15	32	46%
	Branford Railroad Station	205	10/15	209	102%
East Haven	Route 1 at Kimberly Avenue (West Lot)	29	10/15	28	97%
	Route 1 at Kimberly Avenue (East Lot)	20	10/15	20	100%
Guilford	I-95 at Route 77 (exit 58 - East Lot)	20	10/15	4	20%
	I-95 at Route 1 (exit 57)	113	10/15	16	14%
	I-95 at Route 77 (exit 58 - West Lot)	45	10/15	11	24%
	I-95 at Goose Lane (exit 59)	58	10/15	42	72%
	Guilford Railroad Station	176	10/15	193	110%
Madison	I-95 at Route 79 (exit 61)	197	10/15	50	25%
	Madison Railroad Station	110	10/15	183	166%
Meriden	I-691 at Lewis Avenue	55	10/15	closed	0%
	I-691 at State Street	31	10/15	closed	0%
	I-91 at Bee Street	72	10/15	26	36%
Milford	I-95 at Old Gate Lane (exit 40)	75	10/16	33	44%
	I-95 at School House Road (exit 35)	46	10/16	22	48%
	Route 1 at Milford Connector	25	10/16	16	64%
	Route 15 at Wheelers Farms Road (exit 5)	59	10/16	33	56%
	Milford Railroad Station at High Street	444	10/16	608	137%
New Haven	Union Station Garage (1)	1037	10/16	1082	104%
North Haven	Route 40 at Divine Street	109	10/16	112	103%
	Route 5 at Divine Street	103	10/16	113	110%
Orange	Route 15 at Route 34 (exit 58)	154	10/16	100	65%
Wallingford	Route 5 at Wharton Brook Connector	79	10/15	30	38%
	Route 15 at Route 5 (exit 66E)	81	10/15	53	65%
	I-91 at Route 68 (exit 15)	105	10/15	40	38%
	Wallingford Railroad Station	25	10/15	12	48%
West Haven	I-95 at Route 122 (exit 43)	74	10/16	30	41%
TOTAL		3,781		3,142	83%

(1) statistics for Union Station Garage are a daily total of vehicles parked