

COMMUTER PARKING LOTS

Winter, 2009 Data

Municipality	Location	Capacity	Vehicle Count - Feb. 2009		Feb, 2008	Jan, 2007	Jan, 2006	Jan, 2005	Jan, 2004
			Count	Percent Full					
Branford	I-95 at Maintenance Garage (exit 56)	40	5	13%	6	4	7	9	12
	Route 1 at Cherry Hill	124	35	28%	31	29	26	24	11
	I-95 at Route 1 (exit 55)	70	30	43%	29	14	27	19	12
	Branford Railroad Station	205	210	102%	190	231	160	137	70
East Haven	Route 1 at Kimberly Avenue (West Lot)	29	18	62%	18	6	7	11	7
	Route 1 at Kimberly Avenue (East Lot)	20	15	75%	15	12	12	8	11
Guilford	I-95 at Route 77 (exit 58 - East Lot)	113	6	5%	7	5	10	6	5
	I-95 at Route 77 (exit 58 - West Lot)	45	15	33%	6	28	17	6	19
	I-95 at Goose Lane (exit 59)	58	0	0%	20	13	7	11	6
	I-95 at Route 1 (exit 57)	20	21	105%	24	12	12	11	12
	Guilford Railroad Station	176	160	91%	121	174	153	135	79
Madison	I-95 at Route 79 (exit 61)	197	60	30%	65	21	29	16	22
	Madison Railroad Station	110	155	141%	159	139	157	129	93
Meriden	I-691 at Lewis Avenue (exit 6)	55	27	49%	26	10	10	10	8
	I-691 at State Street	31	0	0%	0	2	3	9	2
	I-91 at Bee Street	72	25	35%	25	26	23	24	16
Milford	I-95 at Old Gate Lane (exit 40) - Lot 2	75	35	47%	40	6	6	7	4
	I-95 at School House Road (exit 35)	46	15	33%	15	11	10	11	9
	Route 1 at Milford Connector	25	24	96%	23	20	14	13	7
	Route 15 at Wheelers Farms Road (exit 55)	59	29	49%	37	28	27	20	6
	Milford Railroad Station at High Street	444	449	101%	604	405	424	327	348
New Haven	Union Station Garage (1)	1037	996	96%	1055	1026	1002	976	965
North Haven	Route 40 at Divine Street	109	114	105%	112	53	65	48	37
	Route 5 at Divine Street	103	110	107%	111	69	65	52	42
Orange	Route 15 at Route 34 (exit 58)	154	90	58%	91	65	85	80	58
Wallingford	Route 5 at Wharton Brook Connector	79	29	37%	30	55	24	22	18
	Route 15 at Route 5 (exit 66E)	81	50	62%	53	30	28	35	30
	I-91 at Route 68 (exit 15)	105	38	36%	41	53	45	Closed	28
	Wallingford Railroad Sta	25	11	44%	10	20	19	12	4
West Haven	I-95 at Route 122 (exit 43)	74	32	43%	29	18	40	11	14
TOTAL		3,781	2,804	74%	2,993	2,585	2,514	2,179	1,955

(1) data for Union Station supplied by New Haven Parking Authority

Table 1

COMMUTER PARKING LOTS
Current Use & Peak Utilization
Winter, 2009

Municipality	Location	Capacity	Current Count		
			Date	Vehicle Count	Percent Full
Branford	I-95 at Maintenance Garage (exit 56)	40	2/25	5	13%
	Route 1 at Cherry Hill	124	2/25	35	28%
	I-95 at Route 1 (exit 55)	70	2/25	30	43%
	Branford Railroad Station	205	2/25	210	102%
East Haven	Route 1 at Kimberly Avenue (West Lot)	29	2/25	18	62%
	Route 1 at Kimberly Avenue (East Lot)	20	2/25	15	75%
Guilford	I-95 at Route 77 (exit 58 - East Lot)	20	2/25	6	30%
	I-95 at Route 1 (exit 57)	113	2/25	15	13%
	I-95 at Route 77 (exit 58 - West Lot)	45	2/25	0	0%
	I-95 at Goose Lane (exit 59)	58	2/25	21	36%
	Guilford Railroad Station	176	2/25	160	91%
Madison	I-95 at Route 79 (exit 61)	197	2/25	60	30%
	Madison Railroad Station	110	2/25	155	141%
Meriden	I-691 at Lewis Avenue	55	2/25	27	49%
	I-691 at State Street	31	2/25	0	0%
	I-91 at Bee Street	72	2/25	25	35%
Milford	I-95 at Old Gate Lane (exit 40)	75	2/24	35	47%
	I-95 at School House Road (exit 35)	46	2/24	15	33%
	Route 1 at Milford Connector	25	2/24	24	96%
	Route 15 at Wheelers Farms Road (exit 5)	59	2/24	29	49%
	Milford Railroad Station at High Street	444	2/24	449	101%
New Haven	Union Station Garage (1)	1037	1/27	996	96%
North Haven	Route 40 at Divine Street	109	2/24	114	105%
	Route 5 at Divine Street	103	2/24	110	107%
Orange	Route 15 at Route 34 (exit 58)	154	2/24	90	58%
Wallingford	Route 5 at Wharton Brook Connector	79	2/25	29	37%
	Route 15 at Route 5 (exit 66E)	81	2/25	50	62%
	I-91 at Route 68 (exit 15)	105	2/25	38	36%
	Wallingford Railroad Station	25	2/25	11	44%
West Haven	I-95 at Route 122 (exit 43)	74	2/20	32	43%
TOTAL		3,781		2,804	74%

(1) statistics for Union Station Garage are a daily total of vehicles parked